

General Information

Date & Time: 14, Apr, 2025 10:33

Make	Toyota	Model	Innova
YOM	2023	Mileage	33,156
Registration No.	NHC6419	Chassis No.	PA2JA8EMXN0118196
CC	2.8	Transmission	A/T
Fuel Type	Diesel	Type of Body	Wagon
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	108.6	103	115	108
2	Boot Lid	95.2	96	99	91
3	Roof	97.4	95	93	105/98
4	Left Front Fender	98.0	99	100	95
5	Left Front Door	106.0	104	112	102
6	Center Panel Left				
7	Left Rear Door	103.0	102	104	103
8	Left Back Panel	103.3	105	103	102
9	Right Front Fender	108.3	109	100	116
10	Right Front Door	96.9	92	98	101
11	Center Panel Right				
12	Right Rear Door	95.6	103	93	91
13	Right Back Panel	103.7	97	106	108

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Seat - Grime - Large / (R) Front Seat - Grime - Large / Rear Seat - Grime - Large / Overall Interior - Smell - Yes / Dashboard - Traces of Adhesive Tape - Yes	Remarks Trunk Hood, Rear Gate - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (L) Rear Door, Molding - Scratch & Dent - Large / (L) Front Door, Molding - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Dent - Medium / (R) Front Door, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
with warranty booklet and LTO plate/ with spare tire and jack/ possible flooding/ with tools