

General Information

Date & Time: 15, Apr, 2025 13:26

Make	Toyota	Model	Vios
YOM	2024	Mileage	10,806
Registration No.	DBM2182	Chassis No.	PA1B18F3XP4237964
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	100.3	97	100	104
2	Boot Lid	96.8	95	94	101
3	Roof	91.6	96	91	87/92
4	Left Front Fender	93.3	90	94	96
5	Left Front Door	100.0	100	97	103
6	Center Panel Left				
7	Left Rear Door	99.3	101	100	98
8	Left Back Panel	103.0	107	103	99
9	Right Front Fender	97.2	97	96	99
10	Right Front Door	99.3	111	94	93
11	Center Panel Right				
12	Right Rear Door	103.3	102	99	109
13	Right Back Panel	101.1	97	94	112

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Grime - Small / (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Minimal / (R) Front Seat - Grime - Small / Rear Seat - Grime - Small / (L) Front Seat - Grime - Small / Ceiling - Grime - Minimal	Remarks Rear Bumper, Lamps, Panels - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Medium / (R) Mirror - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Minimal / (L) Front Fender, Molding - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch - Medium / (L) Front Door, Molding - Dent - Small / (L) Rear Fender, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with LTO plate/with spare tire/with warranty booklet/jack and tools/trunk hood cover one pin missing