


General Information

Date & Time: 23, Apr, 2025 14:08

Make	Toyota	Model	Vios
YOM	2024	Mileage	24,513
Registration No.	DBO1541	Chassis No.	PA1B18F30P4237648
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	99.8	106	88	106
2	Boot Lid	92.8	91	92	96
3	Roof	86.0	95	80	82/88
4	Left Front Fender	86.7	87	83	90
5	Left Front Door	93.4	91	96	94
6	Center Panel Left				
7	Left Rear Door	95.5	99	94	93
8	Left Back Panel	98.1	104	96	95
9	Right Front Fender	87.8	89	86	89
10	Right Front Door	91.2	96	88	90
11	Center Panel Right				
12	Right Rear Door	96.8	86	89	116
13	Right Back Panel	96.4	93	92	105

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Large / (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / Rear Seat - Grime - Small / (L) Front Seat - Grime - Small / Ceiling - Grime - Minimal	Remarks Member (Bolted) - Dent - Yes / (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Head Light, High Beam - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes

Inspector Notes
with LTO plate, with warranty booklet, with jack and incomplete tools, with spare tire, headlight issue, reverse light issue