

General Information

Date & Time: 22, Apr, 2025 10:56

Make	Toyota	Model	Vios
YOM	2024	Mileage	13,392
Registration No.	DBO1832	Chassis No.	PA1B18F36P4236486
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	179.6	160	164	215
2	Boot Lid	107.8	92	91	141
3	Roof	89.6	94	88	79/98
4	Left Front Fender	182.6	179	183	186
5	Left Front Door	155.6	165	159	143
6	Center Panel Left				
7	Left Rear Door	147.6	145	131	167
8	Left Back Panel	149.0	160	145	142
9	Right Front Fender	129.3	117	125	146
10	Right Front Door	121.0	138	113	112
11	Center Panel Right				
12	Right Rear Door	81.3	81	74	89
13	Right Back Panel	150.3	129	147	175

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
	
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Minimal / Rear Seat - Grime - Minimal / Ceiling - Grime - Minimal / (L) Front Trim - Grime - Minimal / (L) Front Seat - Grime - Minimal	Remarks Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / (R) Rear Door, Molding - Scratch - Medium / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Mirror - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Rear Wheel, Cover - Cap Missing - Yes / (L) Front Fender, Molding - Repair mark - Yes / Bonnet, Headlight - Repair mark - Yes / Front Bumper, Grille, Lamps - Scratch - Small / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
with LTO plate, no warranty booklet, with jack and no tools, with spare tire