

General Information

Date & Time: 21, Apr, 2025 17:33

Make	Toyota	Model	Innova
YOM	2023	Mileage	17,935
Registration No.	NFB1538	Chassis No.	PA2JA8EMXP0122564
CC	2.8	Transmission	A/T
Fuel Type	Diesel	Type of Body	MPV
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	97.3	104	110	78
2	Boot Lid	91.5	87	95	93
3	Roof	89.0	91	95	85/86
4	Left Front Fender	85.4	90	92	75
5	Left Front Door	93.6	89	96	96
6	Center Panel Left				
7	Left Rear Door	100.1	104	100	97
8	Left Back Panel	103.2	104	98	108
9	Right Front Fender	90.3	86	91	94
10	Right Front Door	89.1	87	89	91
11	Center Panel Right				
12	Right Rear Door	100.8	97	96	109
13	Right Back Panel	100.1	103	97	100

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Large / Rear Seat - Grime - Small / (L) Front Seat - Grime - Medium / (L) Front Floor Mat - Grime - Small	Remarks Front Bumper, Grille, Lamps - Scratch & Dent - Large / (L) Front Fender, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Large / (L) Rear Door, Molding - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch - Large / Trunk Hood, Rear Gate - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Large / (R) Rear Fender, Molding - Scratch & Dent - Large / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch - Large / (R) Front Door, Molding - Scratch & Dent - Large / (R) Front Fender, Molding - Scratch & Dent - Medium / Roof - Dent - Small / (L) Front Wheel, Cover - Cap Missing - Yes / (R) Rear Wheel, Cover - Cap Missing - Yes
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

with warranty booklet/ with spare tire and jack/ with LTO plate/ with tools/