

General Information

Date & Time: 21, Apr, 2025 10:57

Make	Toyota	Model	Vios
YOM	2024	Mileage	9,395
Registration No.	NHM2670	Chassis No.	PA1B18F31P4235634
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	94.3	94	95	95
2	Boot Lid	93.9	91	94	97
3	Roof	85.1	87	85	83/86
4	Left Front Fender	84.2	86	83	84
5	Left Front Door	132.6	130	130	138
6	Center Panel Left				
7	Left Rear Door	90.0	90	86	95
8	Left Back Panel	101.8	112	98	96
9	Right Front Fender	138.0	129	160	125
10	Right Front Door	92.7	97	93	89
11	Center Panel Right				
12	Right Rear Door	132.3	118	140	139
13	Right Back Panel	91.8	86	90	100

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : D
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Grime - Minimal / (L) Front Trim - Grime - Medium / (L) Front Seat - Grime - Medium / (R) Front Seat - Grime - Minimal / Rear Seat - Grime - Small	Remarks (L) Front Door, Molding - Scratch & Dent - Large / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Medium / (R) Rear Door, Molding - Scratch - Large / (R) Front Door, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes

Inspector Notes

with LTO plate/with spare tire/with warranty booklet/with jack/incomplete tools/No reverse camera
