

General Information

Date & Time: 05, Apr, 2025 09:44

Make	Toyota	Model	Vios
YOM	2023	Mileage	35,448
Registration No.	DAS5899	Chassis No.	PA1B18F32N4193049
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.6	108	106	109
2	Boot Lid	103.7	109	97	105
3	Roof	85.7	89	85	83/86
4	Left Front Fender	95.0	102	91	93
5	Left Front Door	95.8	98	97	93
6	Center Panel Left				
7	Left Rear Door	101.5	111	102	92
8	Left Back Panel	104.0	107	103	102
9	Right Front Fender	98.0	103	94	97
10	Right Front Door	101.0	94	112	97
11	Center Panel Right				
12	Right Rear Door	104.0	96	113	103
13	Right Back Panel	100.6	94	99	109

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Seat - Grime - Small / (L) Front Trim - Grime - Medium / (R) Front Seat - Grime - Medium / Dashboard - Worn, Scratch, Cut, Crack - Large / Rear Seat - Grime - Large / (L) Front Floor Mat - Missing - Yes / (R) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / Trunk Room - Worn, Scratch, Cut, Crack - Medium / (R) Front Trim - Grime - Small / Ceiling - Grime - Small	Remarks Trunk Hood, Rear Gate - Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Large / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Crack, Gap - Large / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Front Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Rear Fender, Molding - Dent - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
with LTO plate/with spare tire/with warranty booklet/No jack and tools/reverse camera not function