

General Information

Date & Time: 14, Apr, 2025 13:42

Make	Toyota	Model	Vios
YOM	2024	Mileage	11,040
Registration No.	NHR6770	Chassis No.	PA1B18F31P4230921
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	179.3	157	186	195
2	Boot Lid	108.3	109	109	107
3	Roof	107.9	112	102	127/91
4	Left Front Fender	316.0	347	419	182
5	Left Front Door	145.0	167	142	126
6	Center Panel Left				
7	Left Rear Door	107.0	113	108	100
8	Left Back Panel	109.3	112	111	105
9	Right Front Fender	110.3	117	104	110
10	Right Front Door	90.7	94	86	93
11	Center Panel Right				
12	Right Rear Door	94.5	94	89	100
13	Right Back Panel	99.9	92	97	111

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Trim - Grime - Minimal / Ceiling - Grime - Minimal / (R) Front Trim - Grime - Small	Remarks Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / Member (Bolted) - Rust, Corrosion - Yes / (L) Front Fender, Molding - Repair mark - Yes / Bonnet, Headlight - Repair mark - Yes / Rear Bumper, Lamps, Panels - Repair mark - Yes / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Door, Molding - Dent - Minimal / (L) Front Door, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Large / (R) Front Door, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

with LTO plate/with spare tire/with warranty booklet/with jack/ without tools/No reverse camera