

General Information

Date & Time: 15, Apr, 2025 13:34

Make	Toyota	Model	Vios
YOM	2024	Mileage	8,575
Registration No.	DBP1291	Chassis No.	PA1B18F35R4257980
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	99.1	105	91	101
2	Boot Lid	94.9	88	103	94
3	Roof	88.8	89	84	83/100
4	Left Front Fender	84.8	85	83	86
5	Left Front Door	88.7	83	91	92
6	Center Panel Left				
7	Left Rear Door	92.4	100	94	83
8	Left Back Panel	93.8	103	92	86
9	Right Front Fender	89.5	95	85	89
10	Right Front Door	91.5	94	87	93
11	Center Panel Right				
12	Right Rear Door	92.7	88	90	99
13	Right Back Panel	93.2	98	91	91

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Trim - Grime - Minimal / (R) Front Trim - Grime - Minimal / Ceiling - Grime - Minimal / Rear Seat - Grime - Medium	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with LTO plate, with warranty booklet, with jack,no tools, with spare tire