

General Information

Date & Time: 07, Apr, 2025 09:49

Make	Toyota	Model	Vios
YOM	2024	Mileage	9,370
Registration No.	NHS2204	Chassis No.	PENDING
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	140.0	148	120	152
2	Boot Lid	101.4	96	104	104
3	Roof	112.3	123	118	110/99
4	Left Front Fender	107.0	107	105	109
5	Left Front Door	107.3	109	105	108
6	Center Panel Left				
7	Left Rear Door	113.6	126	107	108
8	Left Back Panel	110.6	118	110	104
9	Right Front Fender	122.3	136	112	119
10	Right Front Door	97.4	100	97	96
11	Center Panel Right				
12	Right Rear Door	108.5	105	97	124
13	Right Back Panel	111.7	115	99	121

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : D
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Large / Trunk Room - Worn, Scratch, Cut, Crack - Minimal / Rear Seat - Grime - Large / (L) Front Trim - Grime - Minimal / (L) Front Seat - Grime - Small / (L) Front Floor Mat - Worked - Small	Remarks Member (Bolted) - Dent - Yes / (R) Front Fender, Molding - Scratch & Dent - Large / (R) Rear Door, Molding - Repair mark - Yes / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Front Door, Molding - Repair mark - Yes / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Roof - Scratch - Small / Bonnet, Headlight - Dent - Large
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes

with LTO plate, with warranty booklet, with spare tire, with jack, no tools, cracked tail lights