


General Information

Date & Time: 15, Apr, 2025 10:09

Make	Toyota	Model	Vios
YOM	2024	Mileage	16,477
Registration No.	NKB8798	Chassis No.	PA1B18F35R4245957
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition




#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	66.1	63	67	68
2	Boot Lid	66.6	63	72	65
3	Roof	77.3	73	73	94/70
4	Left Front Fender	84.1	82	92	78
5	Left Front Door	78.8	84	77	76
6	Center Panel Left				
7	Left Rear Door	73.8	65	77	80
8	Left Back Panel	70.3	56	74	82
9	Right Front Fender	76.6	80	75	74
10	Right Front Door	73.1	79	62	78
11	Center Panel Right				
12	Right Rear Door	69.0	80	57	70
13	Right Back Panel	70.3	66	79	66

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Trim - Grime - Minimal / Rear Seat - Grime - Medium / (L) Front Trim - Grime - Small / (L) Front Floor Mat - Grime - Small / (R) Front Seat - Grime - Minimal / Sunvisor, Sunglass Holder - Grime - Small	Remarks (R) Rear Fender, Molding - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Front Door, Molding - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
with LTO plate/with spare tire/No warranty booklet/No jack/No tools