

General Information

Date & Time: 10, Apr, 2025 13:11

Make	Toyota	Model	Vios
YOM	2025	Mileage	2,834
Registration No.	NHU4129	Chassis No.	PA1B18F32R4269004
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition




#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.0	110	92	104
2	Boot Lid	90.0	85	90	95
3	Roof	84.2	83	85	77/92
4	Left Front Fender	89.3	89	85	95
5	Left Front Door	87.2	86	86	90
6	Center Panel Left				
7	Left Rear Door	90.6	92	91	89
8	Left Back Panel	93.3	92	96	92
9	Right Front Fender	94.7	88	93	103
10	Right Front Door	81.3	87	79	78
11	Center Panel Right				
12	Right Rear Door	85.4	79	85	93
13	Right Back Panel	90.6	89	85	99

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Medium / Rear Seat - Grime - Minimal / Ceiling - Grime - Small	Remarks (R) Front Fender, Molding - Scratch & Dent - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch & Dent - Small / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Rust, Corrosion - Small / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
no LTO plate, with warranty booklet, with jack and tools, with spare tire