


## General Information

Date & Time: 11, Apr, 2025 14:51

<b>Make</b>	Toyota	<b>Model</b>	Rush
<b>YOM</b>	2022	<b>Mileage</b>	123
<b>Registration No.</b>	S8M870	<b>Chassis No.</b>	123456789
<b>CC</b>	1.5	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	SUV
<b>Colour</b>	Black		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.6	113	110	109
2	Boot Lid	99.8	101	99	100
3	Roof	102.2	96	99	109/105
4	Left Front Fender	111.3	113	110	111
5	Left Front Door	114.6	116	112	116
6	Center Panel Left				
7	Left Rear Door	116.0	119	116	113
8	Left Back Panel	102.7	108	102	98
9	Right Front Fender	115.6	114	118	115
10	Right Front Door	111.6	110	110	115
11	Center Panel Right				
12	Right Rear Door	114.0	108	112	122
13	Right Back Panel	100.8	96	103	104

## Overall Evaluation :

**A**

### Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<b>Remarks</b> (L) Front Trim - Grime - Small	<b>Remarks</b> (L) Front Fender, Molding - Scratch - Small
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>
<b>Remarks</b> Defects not found	<b>Remarks</b> Defects not found

<b>Inspector Notes</b>
Brand new unit. With warranty booklet, spare tire, jack and tools. NO LTO PLATE.