

## General Information

Date & Time: 12, Apr, 2025 15:12

<b>Make</b>	Toyota	<b>Model</b>	Yaris Cross
<b>YOM</b>	2024	<b>Mileage</b>	7
<b>Registration No.</b>	Z6F964	<b>Chassis No.</b>	1234567890
<b>CC</b>	1.5	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	SUV
<b>Colour</b>	Green		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	123.0	122	116	131
2	Boot Lid	130.6	116	144	132
3	Roof	131.7	127	129	136/135
4	Left Front Fender	113.3	117	111	112
5	Left Front Door	114.0	104	114	124
6	Center Panel Left				
7	Left Rear Door	117.3	121	114	117
8	Left Back Panel	122.3	124	119	124
9	Right Front Fender	124.6	124	126	124
10	Right Front Door	118.3	118	119	118
11	Center Panel Right				
12	Right Rear Door	114.0	112	112	118
13	Right Back Panel	125.0	127	122	126

## Overall Evaluation :

**A**

### Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<b>Remarks</b> Defects not found	<b>Remarks</b> Defects not found
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>
<b>Remarks</b> Defects not found	<b>Remarks</b> Defects not found

<b>Inspector Notes</b>
Brand new unit. Without jack. With warranty booklet, spare tire and tools. NO LTO PLATE.