

General Information

Date & Time: 12, Apr, 2025 10:49

Make	Toyota	Model	Yaris Cross
YOM	2024	Mileage	27
Registration No.	KD983A	Chassis No.	1234567890
CC	1.5	Transmission	HEV CVT
Fuel Type	Gas	Type of Body	SUV
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	137.6	130	155	128
2	Boot Lid	141.3	133	147	144
3	Roof	129.5	149	142	115/112
4	Left Front Fender	134.6	120	138	146
5	Left Front Door	144.3	130	143	160
6	Center Panel Left				
7	Left Rear Door	144.0	148	133	151
8	Left Back Panel	156.3	155	159	155
9	Right Front Fender	150.6	151	156	145
10	Right Front Door	150.6	170	146	136
11	Center Panel Right				
12	Right Rear Door	148.3	158	134	153
13	Right Back Panel	156.3	156	151	162

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : A
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks Defects not found	Remarks Defects not found
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
No LTO plate/brand new unit/with spare tire/with warranty booklet/No jack and incomplete tools/No seat cover