

General Information

Date & Time: 21, Apr, 2025 18:19

Make	Toyota	Model	Vios
YOM	2025	Mileage	3,503
Registration No.	NHU5858	Chassis No.	PA1B18F31R4273951
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	97.3	100	87	105
2	Boot Lid	92.7	90	91	97
3	Roof	93.2	98	88	92/94
4	Left Front Fender	86.5	91	86	82
5	Left Front Door	90.5	90	93	89
6	Center Panel Left				
7	Left Rear Door	100.6	104	101	97
8	Left Back Panel	97.3	100	94	98
9	Right Front Fender	87.9	84	83	97
10	Right Front Door	90.7	92	87	93
11	Center Panel Right				
12	Right Rear Door	93.7	88	86	107
13	Right Back Panel	101.9	99	97	110

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Door, Molding - Scratch - Large / (R) Front Fender, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Dent - Minimal / (L) Rear Door, Molding - Scratch - Minimal / Bonnet, Headlight - Dent - Minimal / (L) Front Door, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Horn - Issue - Yes

Inspector Notes
with warranty booklet/ with spare tire and jack/ incomplete tools/ with LTO plate/