


General Information

Date & Time: 21, Apr, 2025 18:51

Make	Toyota	Model	Vios
YOM	2024	Mileage	25,093
Registration No.	NFR2605	Chassis No.	PA1B18F30R4252685
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	96.5	100	91	99
2	Boot Lid	88.3	89	88	88
3	Roof	84.5	87	83	86/83
4	Left Front Fender	89.5	94	88	87
5	Left Front Door	88.9	92	85	90
6	Center Panel Left				
7	Left Rear Door	95.8	108	89	91
8	Left Back Panel	100.6	114	95	94
9	Right Front Fender	83.3	83	80	87
10	Right Front Door	85.1	84	84	87
11	Center Panel Right				
12	Right Rear Door	173.3	174	169	177
13	Right Back Panel	91.0	91	86	96

Overall Evaluation :

D

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Large / (L) Front Floor Mat - Cut, Crack - Small	Remarks (R) Rear Door - Repair Traces - Yes / (L) Rear Door, Molding - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch & Dent - Large / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Medium / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (L) Front Door, Molding - Scratch & Dent - Small
Frame Evaluation : D	Functional Evaluation : A
Remarks Rear Side Member & Trunk Room Floor - Condition of Welding, Hardness and Shape of Sealant ? - Yes / Under Spare Box - Bulge (Cuts, Major Deforms) or Corrosion ? - Yes / Under Spare Box - Traces of Bending, or Marks of Panel Repair ? - Yes	Remarks Lamps (Brake, Tail, Fog) - Issue - Yes / Horn - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes
with warranty booklet/ with LTO plate/ with spare tire and jack/ incomplete tools/ broken tail lights / no horn/ trunk cannot be closed/