


General Information

Date & Time: 23, Apr, 2025 08:44

Make	Toyota	Model	Vios
YOM	2023	Mileage	28,964
Registration No.	BAF3250	Chassis No.	PA1B18F36P4204380
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.2	103	100	104
2	Boot Lid	102.1	98	104	104
3	Roof	87.4	93	89	80/89
4	Left Front Fender	94.5	97	92	94
5	Left Front Door	95.8	99	99	89
6	Center Panel Left				
7	Left Rear Door	96.7	102	97	92
8	Left Back Panel	100.2	118	87	96
9	Right Front Fender	96.5	102	97	91
10	Right Front Door	129.1	200	88	99
11	Center Panel Right				
12	Right Rear Door	201.6	201	202	202
13	Right Back Panel	181.3	131	203	210

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Trim - Grime - Medium / (R) Front Seat - Grime - Large / Rear Seat - Grime - Medium / (L) Front Seat - Grime - Small / (R) Front Trim - Grime - Small / Ceiling - Grime - Minimal	Remarks (R) Front Door - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Fender, Molding - Scratch & Dent - Small / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Dent - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Dent - Small / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Wiper - Function - Weak / Spare Key - Issue - Unexist

Inspector Notes
with LTO plate/with spare tire/with jack and incomplete tools/with warranty booklet/No reverse camera/trunk room No cover/right side front door and rear door and rear fender was repainted