


General Information

Date & Time: 23, Apr, 2025 08:45

Make	Toyota	Model	Vios
YOM	2023	Mileage	42,493
Registration No.	NFC7210	Chassis No.	PA1B18F31P4221460
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	95.0	98	94	93
2	Boot Lid	98.3	98	97	100
3	Roof	89.8	89	85	85/100
4	Left Front Fender	90.2	92	87	91
5	Left Front Door	89.7	92	88	90
6	Center Panel Left				
7	Left Rear Door	96.3	95	100	94
8	Left Back Panel	108.4	124	111	90
9	Right Front Fender	94.5	96	95	92
10	Right Front Door	91.0	92	84	97
11	Center Panel Right				
12	Right Rear Door	92.3	93	88	96
13	Right Back Panel	89.2	84	85	99

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Trim - Grime - Minimal / (R) Front Seat - Grime - Small / Ceiling - Grime - Small / Rear Seat - Grime - Small / (L) Front Seat - Grime - Minimal / (L) Front Trim - Grime - Medium	Remarks Member (Bolted) - Rust, Corrosion - Yes / (R) Front Fender, Molding - Scratch & Dent - Large / (R) Front Door, Molding - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Mirror - Scratch - Minimal / Bonnet, Headlight - Scratch - Medium / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / Roof - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
with LTO plate/with spare tire/with jack/No tools/No warranty booklet/No spare tire cover/No reverse camera