


## General Information

Date & Time: 24, Apr, 2025 09:47

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2025	<b>Mileage</b>	8,454
<b>Registration No.</b>	DBQ1999	<b>Chassis No.</b>	PA1B18F36R4267644
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Silver		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.0	113	114	112
2	Boot Lid	114.6	109	120	115
3	Roof	98.8	105	97	96/97
4	Left Front Fender	99.3	100	101	97
5	Left Front Door	100.3	97	103	101
6	Center Panel Left				
7	Left Rear Door	119.6	118	114	127
8	Left Back Panel	226.0	398	155	125
9	Right Front Fender	105.3	108	106	102
10	Right Front Door	99.8	99	101	100
11	Center Panel Right				
12	Right Rear Door	104.6	107	103	104
13	Right Back Panel	103.3	102	99	109

## Overall Evaluation :

**A**

### Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

<b>Interior Evaluation :</b> <span style="float: right;"><b>B</b></span>	<b>Exterior Evaluation :</b> <span style="float: right;"><b>B</b></span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Ceiling - Grime - Small / (R) Front Floor Mat - Grime - Small / Mat Other - Grime - Medium / (L) Front Floor Mat - Grime - Small</p>	<p><b>Remarks</b> (L) Rear Fender - Repair Traces - Yes / (L) Mirror - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Mirror - Scratch - Small / Roof - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small</p>
<b>Frame Evaluation :</b> <span style="float: right;"><b>A</b></span>	<b>Functional Evaluation :</b> <span style="float: right;"><b>A</b></span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>With warranty booklet, spare tire, seat cover, jack and tools. 1 key. With LTO plate.</p>