

General Information

Date & Time: 22, Apr, 2025 13:26

Make	Toyota	Model	Vios
YOM	2021	Mileage	135,274
Registration No.	NEV1909	Chassis No.	PA1B18F30M4155611
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	95.8	96	89	102
2	Boot Lid	97.9	99	98	97
3	Roof	85.8	92	80	85/87
4	Left Front Fender	82.3	84	81	82
5	Left Front Door	90.9	86	89	97
6	Center Panel Left				
7	Left Rear Door	94.4	94	96	93
8	Left Back Panel	91.7	94	91	90
9	Right Front Fender	81.8	82	83	81
10	Right Front Door	83.3	82	83	86
11	Center Panel Right				
12	Right Rear Door	85.8	86	82	90
13	Right Back Panel	92.9	94	87	98

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / (L) Front Seat - Grime - Small / (L) Front Trim - Grime - Small / Ceiling - Grime - Minimal / Overall Interior - Worn as per age - Yes	Remarks Roof - Dent - Minimal / (L) Rear Door, Molding - Scratch & Dent - Minimal / (L) Rear Fender, Molding - Dent - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Dent - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Dent - Small / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Head Light, High Beam - Issue - Yes

Inspector Notes
with LTO plate, with warranty booklet, with jack and incomplete tools, with spare tire, headlight issue