


General Information

Date & Time: 28, Apr, 2025 13:14

Make	Toyota	Model	Vios
YOM	2021	Mileage	27,975
Registration No.	DAV2613	Chassis No.	PA1B18F35M4145740
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	94.5	94	96	94
2	Boot Lid	95.0	91	94	100
3	Roof	89.8	97	83	87/92
4	Left Front Fender	91.5	94	83	98
5	Left Front Door	92.3	95	89	93
6	Center Panel Left				
7	Left Rear Door	89.2	94	91	82
8	Left Back Panel	95.1	100	94	92
9	Right Front Fender	91.9	110	84	82
10	Right Front Door	174.6	159	200	165
11	Center Panel Right				
12	Right Rear Door	87.7	84	80	99
13	Right Back Panel	85.4	84	79	93

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Medium / (L) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / (R) Rear Trim - Cut, Crack - Small / (R) Front Floor Mat - Worked - Small / (R) Front Trim - Grime - Small / (L) Rear Trim - Cut, Crack - Minimal / (L) Front Trim - Grime - Minimal / (L) Front Floor Mat - Worked - Large / Ceiling - Grime - Small	Remarks (R) Front Door - Repair Traces - Yes / (R) Front Fender, Molding - Scratch & Dent - Small / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Dent - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Dent - Small / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch & Dent - Minimal / (L) Rear Door, Molding - Scratch - Medium / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Minimal / (L) Mirror - Scratch - Small / (L) Front Door, Molding - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Repair mark - Yes / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Bonnet, Headlight - Dent - Small / Roof - Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
no warranty booklet, no jack, no tools, no spare tire, with LTO plate, scratches on tail light, audio/radio issue, no reverse camera