

General Information

Date & Time: 28, Apr, 2025 11:00

Make	Toyota	Model	Vios
YOM	2025	Mileage	7,005
Registration No.	CCF7429	Chassis No.	PA1B18F39R4268996
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	94.2	97	95	91
2	Boot Lid	97.1	95	96	100
3	Roof	83.6	85	78	85/87
4	Left Front Fender	85.5	87	88	82
5	Left Front Door	89.3	88	87	93
6	Center Panel Left				
7	Left Rear Door	89.8	102	85	83
8	Left Back Panel	95.2	99	97	90
9	Right Front Fender	95.5	96	97	94
10	Right Front Door	90.5	92	85	95
11	Center Panel Right				
12	Right Rear Door	92.2	88	88	100
13	Right Back Panel	89.0	84	85	99

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Medium / (L) Front Seat - Grime - Small / (L) Front Floor Mat - Grime - Small / (L) Front Trim - Grime - Medium / (R) Front Trim - Grime - Small / (R) Front Seat - Grime - Small / Ceiling - Grime - Small / Trunk Room - Worn, Scratch, Cut, Crack - Minimal	Remarks (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with LTO plate/with spare tire/with warranty booklet/with jack and tools