


General Information

Date & Time: 28, Apr, 2025 13:20

Make	Toyota	Model	Vios
YOM	2022	Mileage	9,546
Registration No.	NEX4790	Chassis No.	PA1B18F39M4163206
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	89.7	94	98	77
2	Boot Lid	92.3	89	93	95
3	Roof	89.2	88	82	96/91
4	Left Front Fender	82.2	76	79	92
5	Left Front Door	88.3	85	89	92
6	Center Panel Left				
7	Left Rear Door	87.6	85	85	94
8	Left Back Panel	92.3	94	95	89
9	Right Front Fender	84.7	79	81	94
10	Right Front Door	90.5	89	88	95
11	Center Panel Right				
12	Right Rear Door	88.8	92	84	91
13	Right Back Panel	89.2	90	88	90

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch & Dent - Medium / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
no warranty booklet/ no tools/ with jack and spare tire/ with LTO plate