

General Information

Date & Time: 23, Apr, 2025 10:07

Make	Toyota	Model	Vios
YOM	2023	Mileage	75,516
Registration No.	NHI7417	Chassis No.	PA1B18F34P4210534
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	93.2	97	89	94
2	Boot Lid	92.2	89	95	93
3	Roof	83.2	88	81	78/87
4	Left Front Fender	79.6	82	80	77
5	Left Front Door	82.7	81	85	83
6	Center Panel Left				
7	Left Rear Door	81.3	84	82	79
8	Left Back Panel	92.5	90	93	94
9	Right Front Fender	84.5	86	84	84
10	Right Front Door	90.8	93	89	91
11	Center Panel Right				
12	Right Rear Door	94.1	89	95	98
13	Right Back Panel	91.0	80	89	104

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Seat - Grime - Large / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Large	Remarks (R) Rear Door, Molding - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch & Dent - Small / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Front Fender, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Dent - Small / (L) Front Door, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Dent - Small / (L) Rear Fender, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes
worn tires/incomplete tools and no warranty booklet/ with spare tire and jack/ with LTO plate/ plate light issue