

General Information

Date & Time: 23, Apr, 2025 15:38

Make	Toyota	Model	Vios
YOM	2024	Mileage	20,449
Registration No.	VAB8914	Chassis No.	PA1B18F30P4234250
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	101.3	106	97	101
2	Boot Lid	99.5	102	93	104
3	Roof	89.3	90	83	92/92
4	Left Front Fender	88.6	88	85	93
5	Left Front Door	92.2	92	93	93
6	Center Panel Left				
7	Left Rear Door	94.6	99	93	92
8	Left Back Panel	101.0	111	95	98
9	Right Front Fender	158.0	150	153	171
10	Right Front Door	129.0	140	117	130
11	Center Panel Right				
12	Right Rear Door	146.0	165	127	146
13	Right Back Panel	137.6	111	129	173

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Medium / (L) Front Floor Mat - Grime - Small / Ceiling - Grime - Small	Remarks (R) Rear Fender - Repair Traces - Yes / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch & Dent - Minimal / (L) Rear Door, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Roof - Scratch & Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
with LTO plate/with spare tire/with tools and jack /No warranty booklet No reverse camera