


General Information

Date & Time: 23, Apr, 2025 15:50

Make	Toyota	Model	Vios
YOM	2025	Mileage	5,955
Registration No.	NKE7809	Chassis No.	PA1B18F34R4266038
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	100.3	106	92	103
2	Boot Lid	95.7	90	100	98
3	Roof	90.0	96	90	89/86
4	Left Front Fender	85.6	88	83	87
5	Left Front Door	95.9	90	91	107
6	Center Panel Left				
7	Left Rear Door	100.9	111	93	99
8	Left Back Panel	102.4	111	100	96
9	Right Front Fender	89.8	91	85	94
10	Right Front Door	92.9	91	98	90
11	Center Panel Right				
12	Right Rear Door	90.8	92	89	91
13	Right Back Panel	96.2	94	87	108

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Trim - Grime - Minimal / (R) Front Trim - Grime - Minimal	Remarks (R) Front Fender, Molding - Dent - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Scratch - Small
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist

Inspector Notes
with LTO plate, with warranty booklet, with jack and tools, with spare tire