

General Information

Date & Time: 28, Apr, 2025 10:20

Make	Toyota	Model	Vios
YOM	2024	Mileage	14,567
Registration No.	NHM4612	Chassis No.	PA1B18F35P4238309
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	92.9	94	89	96
2	Boot Lid	89.4	90	87	91
3	Roof	84.1	90	84	76/86
4	Left Front Fender	80.3	82	78	82
5	Left Front Door	89.1	88	88	92
6	Center Panel Left				
7	Left Rear Door	86.5	98	84	78
8	Left Back Panel	93.4	99	92	89
9	Right Front Fender	98.3	86	88	121
10	Right Front Door	96.1	109	90	90
11	Center Panel Right				
12	Right Rear Door	95.1	84	88	114
13	Right Back Panel	88.7	84	82	101

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / (R) Front Trim - Grime - Minimal / (L) Front Floor Mat - Worked - Large / (L) Front Floor Mat - Grime - Small / (L) Front Trim - Grime - Minimal / Dashboard - Traces of Adhesive Tape - Yes	Remarks (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch & Dent - Small / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
no warranty booklet, with jack, no tools, with spare tire, with LTO plate, scratches on tail light