

General Information

Date & Time: 29, Apr, 2025 11:30

Make	Toyota	Model	Vios
YOM	2024	Mileage	10,205
Registration No.	NEY8825	Chassis No.	PA1B18F39R4258811
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	97.6	98	97	98
2	Boot Lid	104.6	122	95	97
3	Roof	95.8	103	92	93/95
4	Left Front Fender	85.9	85	87	86
5	Left Front Door	85.3	90	82	85
6	Center Panel Left				
7	Left Rear Door	104.3	130	96	87
8	Left Back Panel	96.8	105	91	94
9	Right Front Fender	91.1	88	90	95
10	Right Front Door	90.3	93	93	86
11	Center Panel Right				
12	Right Rear Door	96.4	85	95	109
13	Right Back Panel	104.1	109	100	104

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Medium / (L) Front Seat - Grime - Minimal / (L) Front Floor Mat - Worked - Small / Rear Seat - Grime - Medium / (R) Front Floor Mat - Grime - Medium / Overall Interior - Animal Hair - Yes / (L) Front Trim - Grime - Minimal / Console, Switchs, Vents - Traces of Adhesive Tape - Yes	Remarks (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (L) Mirror - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Dent - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
no warranty booklet, with jack and tools, with spare tire, with LTO plate, scratches on tail light