


General Information

Date & Time: 28, Apr, 2025 17:14

Make	Toyota	Model	Avanza
YOM	2024	Mileage	2,155
Registration No.	DBO9517	Chassis No.	MHFAA1BY5R0027111
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	MPV
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	106.6	105	104	111
2	Boot Lid	89.8	100	94	76
3	Roof	104.4	115	112	98/93
4	Left Front Fender	89.4	91	88	89
5	Left Front Door	105.9	96	106	116
6	Center Panel Left				
7	Left Rear Door	99.2	103	94	101
8	Left Back Panel	103.0	113	109	87
9	Right Front Fender	93.8	97	99	86
10	Right Front Door	97.6	96	97	100
11	Center Panel Right				
12	Right Rear Door	99.2	103	98	97
13	Right Back Panel	93.5	87	91	102

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Worked - Large	Remarks Rear Bumper, Lamps, Panels - Dent - Large / (R) Rear Fender, Molding - Dent - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / (L) Rear Fender, Molding - Dent - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Remote Key & Smart entry - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes

pedal coves removed/ no warranty booklet/ no tools/ with jack/ with spare tire/ with LTO plate