


General Information

Date & Time: 23, Apr, 2025 18:26

Make	Toyota	Model	Vios
YOM	2024	Mileage	2,403
Registration No.	NKB6463	Chassis No.	PA1B18F3XR4244979
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	95.7	99	90	98
2	Boot Lid	97.5	94	99	100
3	Roof	97.7	94	99	94/105
4	Left Front Fender	90.9	94	90	89
5	Left Front Door	88.3	87	86	92
6	Center Panel Left				
7	Left Rear Door	88.9	100	87	80
8	Left Back Panel	94.5	98	93	93
9	Right Front Fender	91.4	92	90	93
10	Right Front Door	93.1	96	90	93
11	Center Panel Right				
12	Right Rear Door	97.8	89	96	108
13	Right Back Panel	97.6	97	90	106

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Small / (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Minimal	Remarks (R) Front Fender, Molding - Repair mark - Yes / (R) Front Fender, Molding - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Repair mark - Yes / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Small
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes

Inspector Notes
with warranty booklet, with jack, incomplete tools, with spare tire, with LTO plate