

General Information

Date & Time: 23, Apr, 2025 17:24

Make	Toyota	Model	Vios
YOM	2024	Mileage	16,436
Registration No.	NKE3821	Chassis No.	PA1B18F32R4259217
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	99.7	104	91	104
2	Boot Lid	103.0	96	111	102
3	Roof	99.4	103	100	93/102
4	Left Front Fender	90.8	93	89	91
5	Left Front Door	96.1	92	95	101
6	Center Panel Left				
7	Left Rear Door	96.6	104	96	90
8	Left Back Panel	104.1	109	95	108
9	Right Front Fender	95.5	96	95	96
10	Right Front Door	95.3	100	94	92
11	Center Panel Right				
12	Right Rear Door	95.7	91	94	102
13	Right Back Panel	105.6	104	106	107

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Large / (L) Front Floor Mat - Worked - Large / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Large	Remarks Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch & Dent - Medium / Trunk Hood, Rear Gate - Crack, Gap - Medium / (R) Front Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Large / (L) Mirror - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Small / (R) Rear Door, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with warranty booklet/ with jack and sparetire/ with LTO plate / with tools