


General Information

Date & Time: 23, Apr, 2025 13:25

Make	Toyota	Model	Vios
YOM	2024	Mileage	27,632
Registration No.	BAG2731	Chassis No.	PA1B18F3XR4250779
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	203.3	204	230	176
2	Boot Lid	133.6	136	134	131
3	Roof	113.0	114	111	109/118
4	Left Front Fender	105.6	104	105	108
5	Left Front Door	147.3	145	139	158
6	Center Panel Left				
7	Left Rear Door	147.0	151	139	151
8	Left Back Panel	112.0	115	115	106
9	Right Front Fender	117.6	118	119	116
10	Right Front Door	120.3	123	115	123
11	Center Panel Right				
12	Right Rear Door	120.0	114	120	126
13	Right Back Panel	118.6	119	111	126

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / (L) Front Seat - Grime - Minimal	Remarks Bonnet - Repair Traces - Yes / Bonnet, Headlight - Repair mark - Yes / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Small / (R) Mirror - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / Trunk Hood, Rear Gate - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch & Dent - Minimal / (L) Front Fender, Molding - Dent - Small / (L) Mirror - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Lamps (Brake, Tail, Fog) - Issue - Yes / Horn - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes
with LTO plate, with warranty booklet, with jack, incomplete tools, no spare tire, dome light issue