

General Information

Date & Time: 23, Apr, 2025 18:52

Make	Ford	Model	Ranger
YOM	2013	Mileage	160,624
Registration No.	BOY06	Chassis No.	MNCLMFF80CW150700
CC	2.2	Transmission	A/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.1	86	96	127
2	Boot Lid	173.6	130	254	137
3	Roof	72.2	72	63	83/71
4	Left Front Fender	111.6	127	108	100
5	Left Front Door	81.0	85	81	77
6	Center Panel Left				
7	Left Rear Door	81.0	85	82	77
8	Left Back Panel	83.7	88	86	77
9	Right Front Fender	85.8	90	81	87
10	Right Front Door	256.6	522	131	117
11	Center Panel Right				
12	Right Rear Door	194.3	348	114	121
13	Right Back Panel	124.7	97	139	138

Overall Evaluation :

D

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Seat - Grime - Large / (R) Front Seat - Grime - Large / Rear Seat - Grime - Large / Mat Other - Missing - Yes / Sunvisor, Sunglass Holder - Missing - Yes	Remarks (R) Front Door - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / (L) Side Gate - Scratch - Large / (L) Front Door, Molding - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Dent - Small / (R) Front Fender, Molding - Scratch & Dent - Medium / (R) Front Door, Molding - Repair mark - Yes / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Repair mark - Yes / (R) Rear Door, Molding - Scratch - Small / (R) Side Gate - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Crack, Gap - Large / Roof - Scratch & Dent - Small
Frame Evaluation : A	Functional Evaluation : E
Remarks Defects not found	Remarks Retractable Mirror - Issue - Yes / Power Window (each) - Stuck, Gap - Yes / Air Conditioner - Function - Weak / Radiator Water Pump - Leak - Yes / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Turn Signal, Hazard Flasher - Issue - Yes / Head Light, High Beam - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes
with LTO plate/ with jack and tools and spare tire /warranty booklet/ no hazard light/ weak aircon/ over heating/ abnormal engine noise/ stuck windows/ weak lights / worn tires