


General Information

Date & Time: 28, Apr, 2025 17:41

Make	Toyota	Model	Vios
YOM	2023	Mileage	93,362
Registration No.	NIJ1806	Chassis No.	PA1B18F31P4204030
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	101.6	103	97	105
2	Boot Lid	100.9	102	98	103
3	Roof	91.6	86	87	89/105
4	Left Front Fender	89.5	88	89	92
5	Left Front Door	95.8	100	97	90
6	Center Panel Left				
7	Left Rear Door	91.7	98	90	87
8	Left Back Panel	98.6	107	95	94
9	Right Front Fender	91.0	97	88	88
10	Right Front Door	93.8	92	96	93
11	Center Panel Right				
12	Right Rear Door	97.2	94	99	100
13	Right Back Panel	91.8	101	88	87

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Medium / (L) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / (R) Front Trim - Grime - Small / (L) Rear Trim - Cut, Crack - Minimal / Overall Interior - Worn as per age - Yes / Ceiling - Grime - Large / Console, Switches, Vents - Traces of Adhesive Tape - Yes / Overall Interior - Smell - Yes / Trunk Room - Loose, Deformed - Large	Remarks (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Mirror - Scratch - Minimal / (R) Rear Fender, Molding - Scratch & Dent - Medium / Trunk Hood, Rear Gate - Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (L) Front Door, Molding - Rust, Corrosion - Medium / (L) Rear Fender, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Small / Member (Bolted) - Dent - Yes / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Bonnet, Headlight - Scratch & Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes
no warranty booklet, with jack, no tools, with spare tire, with LTO plate, cracked tail light, plate light issue