

General Information

Date & Time: 28, Apr, 2025 15:45

Make	Toyota	Model	Vios
YOM	2022	Mileage	21,804
Registration No.	NFH9628	Chassis No.	PA1B18F31N4176954
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.3	107	107	108
2	Boot Lid	99.8	97	100	103
3	Roof	98.2	110	89	92/102
4	Left Front Fender	92.8	90	101	88
5	Left Front Door	95.7	99	95	93
6	Center Panel Left				
7	Left Rear Door	96.5	101	93	95
8	Left Back Panel	106.3	115	108	96
9	Right Front Fender	88.2	89	88	88
10	Right Front Door	99.7	110	99	90
11	Center Panel Right				
12	Right Rear Door	99.6	88	115	96
13	Right Back Panel	95.3	90	88	108

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Medium / (L) Front Seat - Grime - Small / (L) Front Floor Mat - Worked - Small / Rear Seat - Grime - Medium / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Minimal	Remarks (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Dent - Small / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Member (Bolted) - Dent - Yes / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
no warranty booklet, with jack, no tools, no spare tire, with LTO plate