

General Information

Date & Time: 29, Apr, 2025 13:36

Make	Mitsubishi	Model	Mirage
YOM	2023	Mileage	29,545
Registration No.	DBG5009	Chassis No.	PAEA13TJPNA000185
CC	1.2	Transmission	A/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	108.6	109	107	110
2	Boot Lid	94.8	86	99	100
3	Roof	138.5	136	151	140/127
4	Left Front Fender	101.0	101	94	108
5	Left Front Door	97.5	97	100	96
6	Center Panel Left				
7	Left Rear Door	95.2	97	87	101
8	Left Back Panel	104.0	112	100	100
9	Right Front Fender	100.3	91	105	105
10	Right Front Door	121.6	124	117	124
11	Center Panel Right				
12	Right Rear Door	230.0	230	231	229
13	Right Back Panel	196.6	199	202	189

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Mat Other - Grime - Small / Rear Seat - Grime - Small / (R) Front Seat - Grime - Medium / Dashboard - Traces of Adhesive Tape - Yes / Ceiling - Grime - Small	Remarks (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / (L) Rear Fender, Molding - Scratch & Dent - Medium / (L) Front Door, Molding - Dent - Medium / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / Front Bumper, Grille, Lamps - Repair mark - Yes / (R) Mirror - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
no warranty booklet, with jack and tools, with spare tire, with LTO plate, scratches on tail light and headlight