

General Information

Date & Time: 05, Oct, 2024 09:17

Make	Toyota	Model	Vios
YOM	2024	Mileage	6,903
Registration No.	NHN5524	Chassis No.	PA1B18F38R4243474
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	BLACKISH RED MICA		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.0	117	101	109
2	Boot Lid	106.0	103	106	109
3	Roof	99.4	102	103	93/100
4	Left Front Fender	100.4	104	102	95
5	Left Front Door	107.3	105	113	104
6	Center Panel Left				
7	Left Rear Door	105.0	110	104	101
8	Left Back Panel	104.3	107	100	106
9	Right Front Fender	106.0	102	107	109
10	Right Front Door	101.5	97	105	103
11	Center Panel Right				
12	Right Rear Door	108.6	103	114	109
13	Right Back Panel	110.3	101	112	118

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (R) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / (L) Front Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Minimal / (R) Front Door, Molding - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes

more light scratches around the exterior. rear matting has molds.