

General Information

Date & Time: 05, Oct, 2024 13:54

Make	Toyota	Model	Vios
YOM	2024	Mileage	12,238
Registration No.	DBM9496	Chassis No.	PA1B18F39R4244763
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Super Red V		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	130.0	126	124	140
2	Boot Lid	125.6	118	133	126
3	Roof	123.0	131	121	118/122
4	Left Front Fender	116.3	115	119	115
5	Left Front Door	121.6	117	125	123
6	Center Panel Left				
7	Left Rear Door	126.3	130	122	127
8	Left Back Panel	135.0	137	130	138
9	Right Front Fender	114.6	115	105	124
10	Right Front Door	118.6	117	125	114
11	Center Panel Right				
12	Right Rear Door	123.0	115	128	126
13	Right Back Panel	122.0	123	119	124

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (R) Front Fender - Repair Traces - Yes / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / (R) Front Fender, Molding - Crack, Gap - Medium / (L) Front Fender, Molding - Scratch & Dent - Large / Member (Bolted) - Dent - Yes / Rear Bumper, Lamps, Panels - Scratch - Small
Frame Evaluation : B	Functional Evaluation : A
Remarks Right Front Inside Panel (Front Side) - Traces of Bending, or Marks of Panel Repair ? - Yes	Remarks Defects not found

Inspector Notes
swirl marks and hairline scratches present/ tampered front cross support cover/