

General Information

Date & Time: 05, Oct, 2024 15:41

Make	Toyota	Model	Vios
YOM	2024	Mileage	6,396
Registration No.	DBM1843	Chassis No.	PA1B18F39R4238929
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver Metallic 1		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	128.6	130	125	131
2	Boot Lid	132.3	125	134	138
3	Roof	124.7	135	118	115/131
4	Left Front Fender	120.3	128	117	116
5	Left Front Door	117.6	115	117	121
6	Center Panel Left				
7	Left Rear Door	123.0	131	124	114
8	Left Back Panel	127.0	127	128	126
9	Right Front Fender	120.3	112	124	125
10	Right Front Door	110.0	113	109	108
11	Center Panel Right				
12	Right Rear Door	123.6	116	123	132
13	Right Back Panel	137.3	137	123	152

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (R) Rear Fender, Molding - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / (R) Rear Wheel, Cover - Scratch, Corrosion - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
hairline scratches and swirl marks