

General Information

Date & Time: 30, May, 2025 13:05

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	27,037
Registration No.	CCD4156	Chassis No.	PA1B18F38R4256757
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	133.0	127	158	114
2	Boot Lid	117.0	110	125	116
3	Roof	110.5	132	102	100/108
4	Left Front Fender	99.4	100	98	100
5	Left Front Door	102.9	102	112	95
6	Center Panel Left				
7	Left Rear Door	105.3	108	107	101
8	Left Back Panel	117.3	129	112	111
9	Right Front Fender	105.6	102	108	107
10	Right Front Door	103.6	105	106	100
11	Center Panel Right				
12	Right Rear Door	106.6	98	112	110
13	Right Back Panel	107.3	108	101	113

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Small / (L) Front Seat - Grime - Small / Rear Seat - Grime - Medium / (R) Front Seat - Grime - Medium</p>	<p>Remarks (L) Front Door, Molding - Scratch - Large / (L) Rear Door, Molding - Scratch - Large / Trunk Hood, Rear Gate - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Medium</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes</p>

<p>Inspector Notes</p>
<p>With LTO plate and sparetire, Incomplete tools. no warranty booklet and jack. crack tail light and scratch.</p>