

General Information

Date & Time: 05, Oct, 2024 14:28

Make	Toyota	Model	Vios
YOM	2024	Mileage	19,147
Registration No.	DBN3037	Chassis No.	PA1B18F33P4230452
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Alumina Jade Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.6	116	104	118
2	Boot Lid	112.6	110	116	112
3	Roof	102.5	106	104	98/102
4	Left Front Fender	99.3	100	101	97
5	Left Front Door	104.6	106	106	102
6	Center Panel Left				
7	Left Rear Door	103.6	105	105	101
8	Left Back Panel	108.3	121	103	101
9	Right Front Fender	100.3	99	102	100
10	Right Front Door	103.5	100	103	108
11	Center Panel Right				
12	Right Rear Door	105.6	104	105	108
13	Right Back Panel	113.3	108	107	125

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Small / Trunk Room - Loose, Deformed, Grime - Medium	Remarks Trunk Hood, Rear Gate - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
light scratches around the exterior. more scratch and dent at the trunk door.