

General Information

Date & Time: 09, May, 2025 12:22

Make	Honda	Model	BR-V
YOM	2020	Mileage	41,697
Registration No.	NDL4248	Chassis No.	MRHDG1840LP000018
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	SUV
Colour	Pearl White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	125.3	125	126	125
2	Boot Lid	106.6	102	111	107
3	Roof	123.2	114	119	128/132
4	Left Front Fender	117.0	113	118	120
5	Left Front Door	112.0	118	110	108
6	Center Panel Left				
7	Left Rear Door	114.3	123	113	107
8	Left Back Panel	126.6	129	141	110
9	Right Front Fender	117.3	114	122	116
10	Right Front Door	113.6	114	113	114
11	Center Panel Right				
12	Right Rear Door	111.0	109	110	114
13	Right Back Panel	115.6	108	116	123

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Medium	Remarks (L) Rear Door, Molding - Scratch & Dent - Minimal / (R) Mirror - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

Without warranty booklet and sest cover. With spare tire, jack and tools. 1 key. With LTO plate.