

General Information

Date & Time: 14, May, 2025 13:39

Make	Toyota	Model	Hiace
YOM	2025	Mileage	3
Registration No.	DA444B	Chassis No.	JTFNAFAP0S8055416
CC	2.8	Transmission	M/T
Fuel Type	Diesel	Type of Body	Van
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet				
2	Boot Lid				
3	Roof				
4	Left Front Fender				
5	Left Front Door				
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel				
9	Right Front Fender				
10	Right Front Door				
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel				

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks Defects not found	Remarks Bonnet, Headlight - Dent - Medium / Roof - Dent - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
Cluster dents at Hood and roof