

General Information

Date & Time: 29, May, 2025 13:57

Make	Toyota	Model	Wigo
YOM	2022	Odo Meter Reading	24,400
Registration No.	FAJ5938	Chassis No.	MHKA4DF5FNJ066702
CC	1.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	Yellow		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	134.6	133	151	120
2	Boot Lid	138.6	140	120	156
3	Roof	90.3	82	93	89/97
4	Left Front Fender	203.6	191	195	225
5	Left Front Door	144.3	168	127	138
6	Center Panel Left				
7	Left Rear Door	110.3	108	114	109
8	Left Back Panel	103.0	105	101	103
9	Right Front Fender	109.3	109	106	113
10	Right Front Door	105.3	100	109	107
11	Center Panel Right				
12	Right Rear Door	106.6	116	104	100
13	Right Back Panel	114.3	111	112	120

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	B	Exterior Evaluation :	C
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks Rear Seat - Grime - Small / (R) Front Trim - Worked - Small / (R) Front Seat - Grime - Small / Ceiling - Grime - Minimal / (L) Front Trim - Worked - Small</p>		<p>Remarks Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Fender, Molding - Repair mark - Yes / Bonnet, Headlight - Repair mark - Yes / Overall Exterior - Faded(Color, Gloss) - Yes / (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Medium / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Small / Roof - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small</p>	
Frame Evaluation :	A	Functional Evaluation :	C
<p>Remarks Defects not found</p>		<p>Remarks Power Steering - Issue - Yes / Battery - Weak - Yes / Spare Key - Issue - Unexist</p>	

Inspector Notes
with LTO plate, with warranty booklet, with jack and incomplete tools, with spare tire, trunk door not opening, battery weak