

General Information

Date & Time: 02, Jun, 2025 09:58

Make	Toyota	Model	Wigo
YOM	2024	Odo Meter Reading	39,203
Registration No.	BAG2948	Chassis No.	MHKAA1BC7RJ017129
CC	1.0	Transmission	CVT
Fuel Type	Gas	Type of Body	Hatchback
Colour	Yellow		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	126.0	131	123	124
2	Boot Lid	95.2	93	95	98
3	Roof	97.0	95	99	95/99
4	Left Front Fender	105.6	107	93	117
5	Left Front Door	114.0	111	113	118
6	Center Panel Left				
7	Left Rear Door	106.7	114	93	113
8	Left Back Panel	102.6	105	104	99
9	Right Front Fender	114.6	134	107	103
10	Right Front Door	119.3	127	117	114
11	Center Panel Right				
12	Right Rear Door	117.3	125	104	123
13	Right Back Panel	113.0	120	101	118

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Trunk Room - Worn, Scratch, Cut, Crack - Minimal / Rear Seat - Grime - Medium / (R) Rear Trim - Worked - Small / (R) Front Seat - Grime - Medium / (R) Front Floor Mat - Grime - Small / (L) Front Floor Mat - Worked - Small / Ceiling - Grime - Small / (L) Front Seat - Cut, Crack - Medium</p>	<p>Remarks (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Medium / Roof - Scratch - Large / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with LTO plate, no warranty booklet, no jack, incomplete tools, with spare tire</p>