

General Information

Date & Time: 30, May, 2025 10:07

Make	Nissan	Model	Almera
YOM	2017	Odo Meter Reading	78,738
Registration No.	NDE6139	Chassis No.	BDUALBGN17B77544
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	105.0	109	103	103
2	Boot Lid	84.2	88	76	89
3	Roof	102.9	125	93	104/89
4	Left Front Fender	127.3	127	112	143
5	Left Front Door	116.3	125	115	109
6	Center Panel Left				
7	Left Rear Door	121.6	137	107	121
8	Left Back Panel	115.0	118	110	117
9	Right Front Fender	113.6	129	105	107
10	Right Front Door	98.9	97	98	101
11	Center Panel Right				
12	Right Rear Door	103.6	108	98	105
13	Right Back Panel	114.0	111	122	109

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	A	Exterior Evaluation :	C
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks Trunk Room - Worn, Scratch, Cut, Crack - Small / (R) Front Trim - Grime - Small / Dashboard - Worn, Scratch, Cut, Crack - Minimal / (L) Front Trim - Grime - Small / Ceiling - Grime - Minimal</p>		<p>Remarks (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Large / Rear Bumper, Lamps, Panels - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Medium / (L) Rear Door, Molding - Scratch & Dent - Minimal / (L) Front Door, Molding - Scratch & Dent - Minimal / (L) Front Fender, Molding - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch & Dent - Minimal / Bonnet, Headlight - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / Roof - Scratch - Minimal</p>	
Frame Evaluation :	A	Functional Evaluation :	C
<p>Remarks Defects not found</p>		<p>Remarks Air Conditioner - Function - Weak / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>	

Inspector Notes
with LTO plate, with warranty booklet, with jack and incomplete tools, with spare tire, plate light issue, yellowing headlights, no reverse camera