

General Information

Date & Time: 14, Oct, 2024 17:11

Make	Toyota	Model	Avanza
YOM	2022	Mileage	27,445
Registration No.	NFL2443	Chassis No.	MHFAA1BY7N0001412
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	MPV
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	106.0	107	110	101
2	Boot Lid	492.3	575	263	639
3	Roof	117.0	123	117	105/123
4	Left Front Fender	107.6	102	105	116
5	Left Front Door	111.3	109	106	119
6	Center Panel Left				
7	Left Rear Door	113.3	122	109	109
8	Left Back Panel	115.3	125	107	114
9	Right Front Fender	114.0	117	113	112
10	Right Front Door	106.6	109	103	108
11	Center Panel Right				
12	Right Rear Door	114.6	111	109	124
13	Right Back Panel	116.0	101	116	131

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Sunvisor, Sunglass Holder - Grime - Small / Rear Seat - Grime - Small / Trunk Room - Worn, Scratch, Cut, Crack - Small	Remarks Trunk Hood, Rear Gate - Repair Traces - Yes / (L) Front Fender, Molding - Dent - Minimal / (L) Front Door, Molding - Dent - Small / (L) Rear Door, Molding - Scratch & Dent - Minimal / (L) Rear Fender, Molding - Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Minimal / (R) Rear Fender, Molding - Dent - Small / (R) Rear Door, Molding - Dent - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch & Dent - Minimal / Roof - Dent - Large
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Horn - Issue - Yes

Inspector Notes
more dent at the left reardoor. More scratches at the rear trunk. bumperguard loose. more light scratches around the exterior. 2nd row seats has molds.