

General Information

Date & Time: 15, Oct, 2024 14:34

Make	Toyota	Model	Rush
YOM	2019	Mileage	81,138
Registration No.	NEB5172	Chassis No.	MHKE8FE2PKK001610
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Wagon
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.0	101	115	120
2	Boot Lid	104.6	107	105	102
3	Roof	210.5	200	188	230/224
4	Left Front Fender	109.3	106	116	106
5	Left Front Door	100.0	104	103	93
6	Center Panel Left				
7	Left Rear Door	103.1	99	105	105
8	Left Back Panel	112.3	121	112	104
9	Right Front Fender	113.0	109	117	113
10	Right Front Door	105.5	99	100	118
11	Center Panel Right				
12	Right Rear Door	95.9	95	94	99
13	Right Back Panel	105.0	104	101	110

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Steering Wheel - Worn, Peel, Crack - Small / Trunk Room - Worn, Scratch, Cut, Crack - Small / Console, Switchs, Vents - Loose, Deformed, Grime - Medium	Remarks Roof - Repair Traces - Yes / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Mirror - Crack - Cracks / Rear Bumper, Lamps, Panels - Crack, Gap - Medium / Trunk Hood, Rear Gate - Dent - Large
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
reverse camera not function/roof covered carbon sticker/has aftermarket mudflaps/ aftermarket wheels and fender extension/ aftermarket front grill