

General Information

Date & Time: 02, Jun, 2025 08:59

Make	Toyota	Model	Vios
YOM	2017	Odo Meter Reading	64,923
Registration No.	DAH2029	Chassis No.	PA1B18F31H4041905
CC	1.3	Transmission	A/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.6	113	104	112
2	Boot Lid	100.0	92	99	109
3	Roof	110.5	114	103	108/117
4	Left Front Fender	100.3	104	110	87
5	Left Front Door	96.1	102	100	86
6	Center Panel Left				
7	Left Rear Door	96.0	90	98	100
8	Left Back Panel	118.6	107	113	136
9	Right Front Fender	103.0	102	106	101
10	Right Front Door	88.0	84	91	89
11	Center Panel Right				
12	Right Rear Door	91.6	106	87	82
13	Right Back Panel	113.0	109	112	118

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	C	Exterior Evaluation :	E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks Ceiling - Loose, Deformed - Large / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / (R) Front Floor Mat - Missing - Yes / Rear Seat - Grime - Medium / (L) Front Seat - Worn - Yes</p>		<p>Remarks (R) Front Fender - Repair Traces - Yes / (R) Front Fender, Molding - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch & Dent - Large / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Front Door, Molding - Scratch - Large / (L) Rear Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Minimal / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / Member (Bolted) - Dent - Yes / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Dent - Medium</p>	
Frame Evaluation :	B	Functional Evaluation :	A
<p>Remarks Center Floor Panel - Bulge (Cuts, Major Deforms) or Corrosion ? - Yes</p>		<p>Remarks Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>	

Inspector Notes
<p>no warranty booklet, with jack, no tools, with spare tire, with LTO plate, scratches on tail light and headlight, yellowish headlight, right front pillar sidings loose deformed, plate light issue</p>